## This Manual is provided by



## Someone who wanted to help you repair your equipment scanned this manual.

If you would like to help us put more manuals online support us.

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

If your company would like to provide technical information to be featured on this site I will put up on the site as long as I can do it in a non-commercial way.

The site is supported with donation from users, friends and selling of the Galaxy Service Manual CD to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. to pay my costs. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners. This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

A communication of vital interest to every Courier dealer

S-227

December 6, 1973

SUBJECT:

MODIFICATIONS TO COURIER TR-5

Refer to Schematic LI-22

A - On certain mobile antennas, particularly base loaded style, the transmitter may go into self oscillation after the mike button is released. The result is heard as a "garbling" sound in the speaker during receive mode. The oscillation condition may be most apparent when the receiver is "squelched" with the squelch control adjusted just below the noise level.

Cure: Add a 1000 ohm, 1/4 Watt resistor across the primary of A-6 coil located (between Q-10 and Q-11). This size resistor can be added under the PC board. If 1/2 Watt resistor only is available, form the leads about 1" long, tin the coil itself on the top of the PC board.

If this does not cure the problem, replace A-6 coil with CO-35A and add the 1000 ohm resistor as above.

B - Oscillation on outgoing carrier during transmit mode (RF feedback). RF feedback causes a noticeable "squeal" on transmitted carrier.

Cure: Change R-36 (to Q-13) from 10 ohms to 47 ohms.

Also, be sure CE-29 (C-34 on schematic) is well grounded. Reheat ground connection on this capacitor with a soldering iron while pushing upward on the capacitor so that the lug can be resoldered to the PC board. Re-solder the eight ground lugs which connect from the wraparound to the PC board. If improperly soldered to the board, these lugs can (if unsoldered) contribute to RF feedback.

Delete the cabinet screw next to the screw which holds the Q-11 heat sink to the wraparound.

Tape the edge of the wraparound next to the audio output transistors Q-14 and Q-15. This will prevent the speaker frame from touching the wraparound, If grounded, feedback may result.

Ray Dashner
Ray Dashner

Customer Service Mgr.

RD:rt



