
COBRA 21 GTL/LTD, 25 GTL/LTD & PRESIDENT AR/AX 711, AR/AX 44



- 1. Wire up the SPDT switch and the trimmer capacitor (supplied) as shown in Fig.1.
- 2. Cut the trace between the 10.240MHz. crystal and VCl/Clll. Solder the wires from the switch to each side of the cut trace as shown in Fig.2.
- 3. With switch in low position, adjust VC for 27.410 MHz on Ch. 40.
- 4. Switch to high position and check for 27.405. If necessary, adjust VCl or change Clll to obtain this reading.

CHANNEL CONVERSION

- 1. Unsolder and lift the end of R58 opposite pin 8 of IC3.
- 2. Run a wire from terminal Q of the DPDT switch to the lifted end of R58.
- 3. Run a wire from terminal P to where R58 was connected. Also run a wire from P to the red dot post of the epoxy pak. Also Run wire from L to Yel bot on Epoxy Red
- 4. Run a wire from terminal S to pin 1 of the PLL chip.
- 5. Unsolder and remove R69 (off pin 4 of IC2).
- 6. Solder one end of the 47pf capacitor supplied to pin 4.
- 7. Connect the other leg of the 47pf capacitor to terminal K of the switch.
- 8. Run a wire from terminal J to where R69 was connected opposite pin 4.
- 9. Run a wire from the unmarked post of the epoxy pak to ground.

Now this unit will operate on Channels 42-86, 1-40 and on half channels 1A-40A.

