PUBLISHED BY E.F.JOHNSON COMPANY / WASECA. MINNESOTA 56093

## EQUIPMENT AFFECTED

Messenger 123 and 123A Part No. 242-0123-001 and 242-0123-002

## REASON FOR REVISION

Possible on-off switch damage.

## REVISION

Turn volume control switch to the off position before installing push-on knob.

PARTS REQUIRED

None

CHANGE ACTION

Follow this procedure when installing volume control knob.

NATIONAL ASSOCIATION OF SERVICE MANAGERS