

PUBLISHED BY E.F.JOHNSON COMPANY / WASECA, MINNESOTA 56093

## EQUIPMENT AFFECTED

Messenger 109 Part No. 242-0109-xxx

## REASON FOR REVISION

Some C56 capacitors were incorrectly installed at the factory.

An incorrectly installed C56 capacitor causes improper squelch operation in receive condition and no audio in transmit.

## REVISION

Reinstall or replace incorrectly installed C56.

## CHANGE ACTION

This error has been corrected at the factory.