SUBJECT: Citizen's Band

MODEL: 14T300/301

DATE: April 29, 1977

## RСЛ

## FIELD BULLETIN #77-005

TO: ALL CB/SCANNER WARRANTY REPAIR CENTERS

SUBJECT: CORRECTIONS TO BULLETIN #77-004

## Please revise bulletin #77-004 as follows:

Item 2 -- a) Adjust RV104 on 14T300 so that meter pointer reads 3.8 watts.

b) Adjust RV501 on 14T301 so that meter pointer reads in the center of the red zone.

Item 3 -- Disregard this item completely; R109 remains 100K.

R. J. Nelson, Manager Field Quality Assurance

RJN/1kr