

PUBLISHED BY E. F. JOHNSON COMPANY | WASECA, MINNESOTA 56093

EQUIPMENT AFFECTED

Messenger 122, 123, 123A (A-C revision) and 223 Part No. 242-0122-xxx, 242-0123-001, 242-0123-002, and 242-0223-xxx

REASON FOR REVISION

Low frequency oscillator crystal part numbers have been changed on some models.

REVISIONS

Messenger 123, 123A (A-B revision) and 223 low frequency oscillator crystal part numbers are: 519-0023-001/-008.

Messenger 122 and 123A (C revision) low frequency oscillator crystal part numbers are: 519-0023-101/108.

CHANGE ACTION

When replacing crystals, order the proper replacement crystal by revision letter.