

This Information Is Provided By
CBTricks.com

Pace Service Bulletin #0011

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners.

This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

For information on how to Support CBTricks.com

<http://www.cbtricks.com/support/>

((P)) PATHCOM INC.
PACE TWO-WAY RADIO PRODUCTS

PDSR-1
DATE OF ISSUE 5-21-76

24049 SOUTH FRAMPTON AVENUE, HARBOR CITY, CALIFORNIA 90710 • TEL. (213) 325-1290 • TWX 910 347 7310 PATHCOM HRBO

SERVICE BULLETIN NO. 0011


1000 B & M NEW PC BOARD

In our continuing program to improve PACE products, we have changed the printed circuit board in the Sidetalk 1000 units. This change to a double sided printed circuit board removed a number of wire bundles and a few components.

This Service Bulletin contains an updated parts locator for both base and mobile units and a schematic on the mobile.

Some Owners Manuals still show the schematic and parts locator for the single sided printed circuit boards. We anticipate a change in the Owners Manual shortly to reflect the new circuit board.

The double sided boards started appearing in early March 76 and new Owners Manuals started being supplied in May 76.



Main Board Parts Locator Both Models
(Component Side)