

Radio : Magnum S9 50W Version
Date : September 2007

Complaint:

Audio feedback via the AMT when on SSB and the AMT is turned down fully. No feedback when on AM or FM.

Solution:

Change C-38 on the echo board to 470uf 16v cap