

This Information Is Provided By  
***CBTricks.com***

Pace Service Bulletin #7364

**Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!**

**Modifications are provided for information purposes only!**

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners.

This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

**Thank you for any support you can give.**

For information on how to Support CBTricks.com

<http://www.cbtricks.com/support/>

# **((P)) PATHCOM INC.**

## **PACE TWO-WAY RADIO PRODUCTS**

24049 SOUTH FRAMPTON AVENUE, HARBOR CITY, CALIFORNIA 90710 • TEL. (213) 325-1290 • TWX 910 347 7310 PATHCOM HRBO  
SERVICE BULLETIN #7364

(Replaces SB#7273)

TO: PACE FIELD SERVICE

SUBJECT: COMMERCIAL FM & TV INTERFERENCE ON PACE CB MODELS:  
CB 223, CB 2376, CB 2376A, CB 2300, CB 76, & CB DX2300B

Upon rare occassion, a very strong FM signal from commercial FM broadcast or television or a combination of these will cause interference to the above CB models. Should this occur, the following trap circuit may be placed in line between the relay and C1 of the receiver input circuit. The trimmer capacitor is adjusted for minimum interference. The parts are commonly available, and are also stocked by the PACE factory.

<u>PART NUMBER</u>	<u>USER COST</u>
19-0136 (2-8 pF trimmer capacitor)	\$1.90
17-0065 (.47 micro H RF choke)	2.20

